




COOPER



RMC Chalk Conveyor

Cooper Chalk Up Another Success

The Application Problem

Critical to the chalk quarrying operation at RMC Rugby, Kensworth Quarry is the recycled material conveyor. The inclined conveyor which is an integral component of site conveying system, has the tail drum situated in a pit.

Due to the pit location, water tended to collect in this area and entered the tail drum bearings. As a result, the SNL 515 - 612 bearing fitted to the 100mm shaft failed every 2 to 3 months causing problems for both operations and maintenance staff.

If the recycled material conveyor is stopped for any reason, the productivity of entire site is affected, which has a negative impact on the Kensworth site production.



The Cooper Split Solution

To rectify the problem, Cooper recommended a BCP 100mm GR (fixed) and EX (expansion) bearings for the tail drum application.

The water penetration problem was solved by using the a Cooper SRS seal which is suitable for wet but not submerged applications. The SRS seal is available in high and low temperature versions (-20°C to 100°C).

RMC Rugby Kensworth lubricate the bearings to Cooper specifications which has resulted in the Cooper bearings providing continuous operation for over a year (at time of printing) with no problems.

The Cooper hallmark split to the shaft feature permits inspection and maintenance to be carried out at the shortest possible time. The Cooper solution has solved an operational problem and reduced maintenance and inspection time, which makes a positive contribution to profitability.



Photographs with permission of RMC Group

Customer Service Centres

UK, Africa, Asia, Australasia and the Middle East

Cooper Roller Bearings Co Ltd
Wisbech Road
King's Lynn
Norfolk PE30 5JX
England.
Telephone +44 (0) 1553 763 447
Fax +44 (0) 1553 761 113

Europe and South America

Cooper Geteilte Rollenlager GmbH
Postfach 100 423
Oberbenrader Str 407
47704 Krefeld
Germany.
Telephone + (49) 2151 713 016
Fax +(49) 2151 713 010

USA and Mexico

The Cooper Split Roller Bearing Corp
5795 Thurston Avenue
Virginia Beach, VA 23455 - 3378
USA.
Telephone 757 460 0925
Fax 757 464 3067

Canada

Cooper-Grainger Canada Inc
5875 Coopers Avenue
Mississauga
Ontario L4Z 1R9
Canada
Telephone 905 890 2266
Fax 905 890 2269